



Skupa E Mobility  
2129/268, Motilal Nagar No. 1,  
Link Road, Goregaon (w), Mumbai - 400104  
Contact - 9892141353 / 91367024556 / 9136011005  
Mail id - skupaebike@gmail.com

**AMPERE**  
By GREAVES

### Job Card / Estimate

Job Card No.: JC-G-1077

Date & Time: 08-03-2023 14:46:07

CUSTOMER DETAILS		Vehicle Details
Customers Name: ULHAS DATTATRAY SHAH Name of Contact person: Mr Tejas shah Mobile No: <a href="tel:7738678091">7738678091</a> Vehicle Model: Magnus Ex		Chassis No: MCPM11200CCF17188 Vehicle Registration No.: MH05EW4126 Vehicle Km: 4303 Service Type: 3rd free service
CUSTOMER REQUEST/COMMENTS		Any Damage or other details
Horn Not working, Headlight not working, Tail light not working, Side indicator not working, Display issue, Range issue, Fiber body damage, Boot light issue, Self strat switch issue, cut off issue, Horn, Boot light not off, Drl not working, Battery Patti screw, Key get stuck into ignition lock, Vehicle wobble while ridding		Rear panel top damaged , scratches on front fender , scratches on left side panel
<b>Remark (if any)</b> - Vehicle harness wire nibbled by rat. resulting in to DC converter failuer. As per norms converter is out of warranty. We have changed DC FOC under goodwill.		<b>Received With Vehicle</b> - Charger Received , Battery Received , No helmet with vehicle, , Battery Patti received , 2 battery screws received , tool kit received , Single key received

Parts Estimate				Service Estimate		
No	Spare Part Name	Qty	Price	No	Service Description	Price
1	MAG FRONT FENDER-ABS-GALACTIC GREY	1	₹1,345	1	Labour Chages	₹150
2	Mag / Zeal-Converter-48/60V-12V DCDC	1	₹0	2	Harness Wiring Repair	₹500
3		0		3	3rd free service	₹0
4		0		4		
5		0	₹0	5		
6		0	₹0	6		
7				7		
8				Total Spares Estimate		₹1,345.00
9				Total Service Estimate		₹650.00
10				Total estimated Cost		₹1,995.00

Estimate is only approx. cost based on initial inspection and actual cost may vary as per the actual work done

Name of the technician: Ganesh	Received By : Sudeep
<ul style="list-style-type: none"> <li>- Information given above is correct to carry out repair work</li> <li>- Don't leave any personal belongings like helmet, tool kit, wallet, cash, card, mobile or any valuable item in the vehicle.</li> <li>- Parking Charges applicable if delayed for approval and not collecting vehicle</li> </ul>	 Customer's Signature

I authorize and allow the workshop to dismantle & assemble all relevant aggregate(s) of the vehicle in order to diagnose the root cause and carry out necessary repairs using required spare parts as per the terms of warranty policy and Job card. I am fully aware that my vehicle shall be stored, driven and repaired at my own risk and cost. I agree that for any loss or damage caused to my vehicle or delay in repair or delivery in the event of any force majeure situation or fire or accident or government directives or epidemic / pandemic disease or any unforeseen circumstances, Ampere by Greaves Electric Mobility Private Limited (OEM) & Skupa E Mobility ( Dealer) shall not be responsible. I have also read and understood the terms & conditions mentioned overleaf of the job card and agree to abide by the same.

Gate pass

Job Card No.: JC-G-1077 Date & Time: 08-03-2023 14:46:07

Customer name : ULHAS DATTA SHAH

Vehicle Chassis No.: MCPM11200CCF17188

Vehicle Reg. No.: MH05EW4126 Model: Magnus Ex

Name & Mobile no. of Receiver :

Date & Time of delivery :

Signature of receiver : \_\_\_\_\_

**\*\*Carry this slip at the time of delivery. Vehicle will be delivered only after full payment and submission of this slip\*\***

Vehicle Received Photos



#### Terms & Conditions